UNIT Video Switching Unit (VSU) SHUTTLE CCTV DWG NO. 2294823-502. 504 FMEA NO. 1,2,2\_ CRITICAL ITEMS LIST CRITICALITY 2/2 FAILURE EFFECT FAILURE MODE AND RATIONALE FOR ACCEPTANCE ON END ITEM CAUSE DESIGN FEATURES No video signal to any No video output destination including The VSU is a microprocessor-based video switching unit using an RCA 1802 on-board monitors and Causes: microprocessor, CMOS RAM, and TTL PROM. Computer I/O, decoding logic, digital audio downlink. (1) Command failure on and switch control circuitry are implemented in CMOS CD4000 series logic to minimize microprocessor, 1/0. power dissipation. The design incorporates DMOS FET devices (SD211s) purchased to Worst Case: A1-2592389-501 or 2294889-502 an RCA spec control drawing (SCD) as the basic video switch element. Video (2) Timing logic, Loss of mission split-screen capability incorporates glass delay line modules procured from Logic board (VSU A3) critical video. Microsonics (originally Corning) to an RCA SCD. The video amplifier design uses 2592392-504 or 2294891-502 monolithic NE5539 wideband op amps in a fashion similar to the sync amp design (3) Switch matrix short on output employed in the RCU. Amplifier A6, A7, or A8, 2294894-502 Parts were required to be JAN reliability level parts of their equivalent. Part (4) Power bus short, all VSU boards selection falls into three categories: (1) JAN or better parts from the Military QPL, (2) Parts demonstrated to NASA to be equivalent to JAN level via test data (e.g., CD4000/3W series parts), or (3) Parts procured to an RCA spec control drawing which calls out tests and screening to effect JAN equivalency. BARE BOARD DESIGN (A6, A7, A8) The design of the associated A6, A7, and A8 boards is constructed from laminated copper-clad epoxy glass sheets (NEMA G-10) Grade FR-4), PER MIL-P-55617A. Circuit connections are made through printed traces which run from point to point on the board surfaces. Every trace terminates at an annular ring. The annular ring surrounds the hole in which a component lead or terminal is located. This ring provides a footing for the solder, ensuring good mechanical and electrical performance. Its size and shape are governed by MIL-P-S5640 as are trace widths, spacing and routing. These requirements are reiterated specifically in drawing notes to further assure compliance. Variations between the artwork master and the final product (due to irregularities of the etching process) are also controlled by drawing notes. This prevents making defective boards from good artwork. Holes which house no lead or terminal, but serve only to electrically interconnect the different board layers, contain stitch bars for mechanical support and increased reliability. The thru holes are drilled from a drill tape thus eliminating the possibility of human error and allowing tight control over hole and annular ring concentricity, an

important reliability criterion. After drilling and etching, all copper cladding is tin-lead plated per MIL-STD-1495. This provides for easy and reliable soldering at

the time of board assembly, even after periods of prolonged storage.

REVISED 5-7-87

	•			
FMEA NO. 1.2.2  CRITICALITY 2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>Video Switching Unit (V</u> DWG NO. <u>2294823-502. 504</u> SHEET <u>2</u> OF <u>7</u>	
FAILURE MODE AND FAILURE EFFECT CAUSE ON END ITEM		RATIONALE FOR ACCEPTANCE		
Auses: (1) Command failure on microprocessor, I/O, A1-2592389-501 or 2294889-502 (2) Timing logic, Logic board (VSU A3) 2592392-504 or 2294891-502 (3) Switch matrix short on output Amplifier A6, A7, or A8, 2294894-502 (4) Power bus short, all VSU boards	No video signal to any destination including on-board monitors and downlink.  Worst Case: Loss of mission critical video.	DESIGN FEATURES  BOARD ASSEMBLY DESIGN (A6, A7, A8)  All components are installed in a manner which assur. Component leads are pre-tinned, allowing total wetting are formed to provide stress relief and the bodies on Special mounting and handling instructions are inclusived after final assembly. The board is coated with uretinumidity and contamination.  BOARD PLACEMENT (A1, A3, A6, A7, A8)  The (A1, A3, A6, A7, and A8) boards are secured in the bygold-plated beryllium copper card guides. Connect with blind-mated connectors. Disengagement during 1 spans the board's free edge.  BARE BOARD CONSTRUCTION (A1, A3)  The boards are of "welded wire" construction. At the distinguish it from a normal PC board except that how generally are not connected to PC traces. Only those ground potentials to the ICs are on PCs. An annular board where each power and ground pin is located. If the trace like any other component lead. Aside from a construction techniques used in PC board layout appears to be provided by the construction techniques used in PC board layout appears. Power and ground pins, as well as complace. Discreet components (resistors, diodes, capabilifurcated terminals, where they are soldered. Flat lead-by-lead, to the tops of the weld pins. After we trimmed away. Circuit connections are made using #3 wire is welded to the pin surfaces on the board back using a machine which is tape driven, thus eliminating the due to operator error. All wiring & circuit perform box-level installation. After successful testing, coby drawing notes and the assembly is coated with ure.  The board is inserted in the box on card-edge guides PC boards.	ng of solder joints. All leads f large components are staked. ded in each drawing required hane which protects against he electronics assembly tions are made to the mother board aunce is prevented by a cover which will take weld pins e pins which bring power and ring surrounds the hole in the hese pins are then soldered to this feature, all design ply.  eral hundred solderable or mactor pins, are soldered in citors) are attached to pack ICs are welded, lding, extra lead material is D AWG nickel weld wire. The side. All wire welds are done ing the possibility of miswiring ance is tested prior to components are staked as required thane.	

FMEA NO. 1.2.2			SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>Video Switching Unit (V</u> DWG NO. <u>2294823-502</u> , <u>504</u> SHEET3 OF7		
CRITICALITY 2/2			• -	JIEL		
FAILURE MODE AND FAILURE EFFECT ON END ITEM			RATIONALE FOR ACCEPTANG			
video output  uses: ) Command failure on microprocessor, I/O, A1-2592389-501 or 2294889-502 ) Timing logic, Logic board (VSU A3) 2592392-504 or 2294891-502 ) Switch matrix short on output Amplifier A6, A7, or A8, 2294894-502 ) Power bus short, all VSU boards		OUALIFICATION TEST  for Qualification Test Flow, see Table 2 located at the front of this book.  ACCEPTANCE TEST  The CCTV systems' VSU is subjected to the following testing:  • Vibration: 20-80Hz: 3 dB/Oct-rise from 0.01 G <sup>2</sup> /Hz to 0.04 G <sup>2</sup> /Hz  80-350 Hz: 0.04 G <sup>2</sup> /Hz  350-750 Hz: 3 dB/Oct-Fall to 0.018 G <sup>2</sup> /Hz  750-1000: 0.018 G <sup>2</sup> /Hz  1000-2000: 3 dB/Oct-Fall to 0.009 G <sup>2</sup> /Hz  Test Duration: 1 Minute per Axis  Test Level: 6.6 Grms				
		The VSU may not	100° f: Time to stablize equipment p 0° f: Time to stablize equipment p 100° f: Time to stablize equipment p Test Flow, see Table 1 located at the t have been subjected to the vacuum con	lus 1 hour lus 1 hour front of this book · - ·		
	·	health of all through the RCL decoder. The tability to rout	of that CCTV components are operation the command related components from the J, through the sync lines to the Camera test must also verify the camera's ability to rmed to verify the command path.	PHS (A7A1) panel switch, /PTU, to the Camera/PTU command ity to produce video, the VSU's		
		Pre-Launch on Orbiter Test/In-Flight Test				
		2. Via the test of tes	CCTV System. The PHS panel, select a monitor as destions source. "Camera Power On" command from PHS panet "External Sync" on monitor. Note the ronized (i.e., stable raster) then this ceiving composite sync from the RCU and ronized video. Pan, Tilt, focus, Zoom, ALC, AND Gamma the monitor or direct observation) veriful the command camera under the command camera under the panet of the panet of the command camera under the panet of	<ol> <li>at if video on monitor is indicates that the camera that the camera is producing commands and visually (either y operation.</li> </ol>		
233R <u>←</u> .		9. Send ' 10. Repeat This p	ve video routed to downlink. "Camera Power Off" command via PHS pane t Sleps 3 through 9 except issue comman proves that the CCTV equipment is opera	ds via the MDM command path.		

FMEA NO. 1.2.2 CRITICALITY 2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT VIO DWG NO. SHEET	<u>2294823</u>	3-502	Unit (VS 504 7
FAILURE MODE AND CAUSE No video output  Causes: (1) Command failure on microprocessor, 1/0, A1-2592389-501 or 2294889-502 (2) Timing logic, Logic board (VSU A3) 2592392-504 or 2294891-502 (3) Switch matrix short on output Amplifier A6, A7, or A8, 2294894-502 (4) Power bus short, all VSU boards	FAILURE EFFECT ON END ITEM No video signal to any destination including on-board monitors and downlink.  Worst Case: Loss of mission critical video.	Procurement Control - The VSU Parts and hardware items vendors and suppliers, which meet the requirements set Quality Plan Work Statement (WS-2593176). Resident DCA procurement documents to establish the need for GSI on Incoming Inspection and Storage - Incoming Quality inspectived materials and parts. Results are recorded by drawing and control numbers for future reference and tresubjected to incoming acceptance tests as called for in Test Instructions. Incoming flight parts are further proceedings of the exception the DPA and PIND testing is not performed inspected per PAI 316 - Incoming Inspection Instructions, Processing Incoming or Purchased Parts Designated for fare delivered to Material Controlled Stores and retaine until fabrication is required. Non-conforming material Board (MRB) disposition. (PAI-307, PAI IQC-531).  Board Assembly & Test - Prior to the start of VSU board verified to be correct by stock room personnel, as the a kit. The items are verified again by the operator when the checking against the as-built-parts-list (ABPL). DCAS are designated for all printed circuit, wire wrap and wharness connectors for soldering wiring, crimping, sold workmanship prior to coating of the component side of b Specific VSU board assembly and test instructions are papplicable documents are called out in the Fabrication (FPR-2294023) and parts list PL 2294823. These include Process Standard RTV-566 2280881, Process Standard - Bo Specification Soldering 2280749, Specification Name Pla Specification Expoxy Adhesive 2010985, Specification - Specification Expoxy Adhesive 2010985, Specification Fxpoxy Adhesive 2010985, Specification - Specification - Workmanship 8030035, Specification Bond	are procurs forth in the Spersonner selected particular and response in the Sperson selections are letter and PAI 315 - processed in the Sperson selected with the Sperson selected with the Sperson selected with the Sperson selected in the Sperson	he CCTV I review arts (P) e made ( tained   Incomin n accord ctronic cal iter anical   12 - Pro Accept ecified for Mad all iter accumula s the ki Inspect and qua sleeving and Rece ection I ro Tape tion 1926 king 226 compour 80076,	contra- w all AI 517) on all in file EEE par ng Inspidance w Parts, ns are items, icedure ted ite condit terial if by ion Poi ality g of ha g notes ord List 226 2280886 60167, and 2026	by ts are ection ith with PAI for ms ions Review  form nts rnesses , and 95906,
		1				

			WEYISED S 7 C
FMEA NO. 1.2.2  CRITICALITY 2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>Video Switching Unit (VS</u> DWG NO. <u>2294823-502</u> , <u>504</u> SHEET5
FAILURE MODE AND CAUSE No video output  Causes: (1) Command failure on microprocessor, I/O, A1-2592389-501 or 2294889-502 (2) Timing logic, Logic board (VSU A3) 2592392-504 or 2294891-502 (3) Switch matrix short on output Amplifier A6, A7, or A8, 2294894-502 (4) Power bus short, all VSU boards	FAILURE EFFECT ON END TIEM  No video signal to any destination including on-board monitors and downlink.  Worst Case: Loss of mission critical video.	QA/INSPECTION (Continued)  VSU Assembly and Test  An open box test is performed per TP-IT-22944832, and a TP-AT-2294823, including vibration and thermal vacuum. witnessed, traceability numbers are recorded and calibr to use. RCA quality and DCAS inspections are performed specified FPR operations in accordance with PAI-204, PA DCAS personnel witness VSU button-up and critical torque monitor acceptance tests and review test data/results. after all repair, rework and retest.  Preparation for Shipment - The VSU is packaged according standard for packaging and handling guidelines. All reassembly drawing, parts list, ABPL, test data, etc. is documentation folder assigned specifically to each asseretained for reference. An EIDP is prepared for each verguirements of WS-2593176. RCA QC and DCAS personnel packing and marking, and review the EIDP for completence.	In Acceptance Test per Torques are specified and lated tools are check prior at the completion of I-205, PAI-206, and PAI-217. Ing. RCA and DCAS personnel These personnel also inspect g to 2280746. Process lated documentation including gathered and held in a mbly. This folder is SU in accordance with the witness crating, packaging,

		·	KEVISED 3-7-07
FMEA NO1.2.2 CRITICALITY _2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>Video Switching Unit (VSU)</u> DWG NO. <u>2294823-502.504</u> SHEET <u>6</u> OF <u>7</u>
FAILURE MODE AND CAUSE  No video output  Causes: (1) Command failure on microprocessor, I/O, A1-2592389-501 or 2294889-502 (2) Timing logic, Logic board (VSU A3) 2592392-504 or 2294891-502 (3) Switch matrix short on output Amplifier A6, A7, or A8, 2294894-502 (4) Power bus short, all VSU boards	FAILURE EFFECT ON END ITEM No video signal to any destination including on-board monitors and downlink.  Worst Case: Loss of mission critical video.	FAILURE HISTORY  TOR W0911-Log 0348 VSU - 2294823-501 S/N F001  Description: Acceptance Test Failure, Board Level ground pins were found shorted together. Bench temperature.  Cause: These shorts were caused by the Al board PWN (1st item testing).  Corrective Action: ECN was written to correct PWMP per ECN #CCT-586.  All Al boards built prior to or subsequent to this freworked per ECN CCT-586.	, Ambient Environment. Unit power & test, board assembly, ambient  P traces, design error  & net list. Board reworked per

			•
FMEA NO. 1.2.2  CRITICALITY 2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>Video Switching Unit (VSU</u> DWG NO. <u>2294823-502</u> , <u>504</u> SHEET
FAILURE MODE AND CAUSE  No video output  Causes: (1) Command failure on microprocessor, I/O, A1-2592389-501 or 2294889-502 (2) Timing logic, Logic board (VSU A3) 2592392-504 or 2294891-502 Switch matrix short on output Amplifier A6, A7, or A8, 2294894-502 (4) Power bus short, all VSU boards  FAILURE EFFECT ON END ITEM No video signal to a destination including on-board monitors and downlink.  Worst Case: Loss of mission critical video.		OPERATIONAL EFFECTS  Loss of video. Possible loss of major mission objective or other required cameras.  CREW ACTIONS  If possible, continue RMS operations using alternative CREW IRAINING  Crew should be trained to use possible alternatives to MISSION CONSTRAINI  Where possible, procedures should be designed so they occiv.	ves due to loss of RMS cameras visual cues. CCTV.